

Company:	Generic	Prepared by (Inc. Designation):	T Millen
Address:		Date Prepared:	07/02/2019
Contact Person:	Site Manger	Review Date (If Applicable):	07/02/2022
Area or Department:	As Required	Signature of Assessor:	
Work Activity:	Service & Repair of Perfect Fry System Fire Extinguisher		IN
		L	\mathcal{M}

			0 - 1
Key to Assessment:	LOW	MEDIUM	<u>HIGH</u>
	Minor Impact/Damage Quickly Repaired	Moderate Impact/Partial Loss of Operations	Disaster/Very Serious Consequences

Hazard/s	People at Risk	Precautions/Controls Required to Reduce the Level of Risk to the Lowest Practicable Level	Residual Risk Low/Medium/High
Manual Handling of Tools & Equipment	Fire Queen Technician	 Use of wheeled trolley when practical Sharing of the load Competent Technicians with proper training Allow sufficient time to set up etc 	Low
Use of Tools & Equipment	Fire Queen Technician	 Use of company provided tools only Safety testing & calibration where required Competent Technicians with proper training Regular visual checks before & during operations 	Low
Asbestos Used in Construction	Fire Queen Technician Customer Employee	 Work Permit in place Examination of Asbestos Register Competent Technicians with proper training Stop work if suspect material is encountered & instigate contamination protocol 	Low
Electricity Supply	Fire Queen Technician	 Work Permit in place Disconnection of electricity supply pre-work Rubber soled safety footwear 	Low



Hot Cooking Oil used in Fryer	Fire Queen Technician	 Unit must not have been used on day of service work Oil must be cool pre-work Check display to ensure unit is switched off Disconnection of plug from electricity outlet 	Low
Stored Energy Release of Extension Spring	Fire Queen Technician	 Use of Eye Protection Use of Gloves Procedure Practice in Controlled Conditions 	Low
Pinching of Hand by Extension Spring	Fire Queen Technician	 Use of Gloves Procedure Practice in Controlled Conditions 	Low
General Access Walkways/Routes Slips/Trips/Falls/Obstacles	Fire Queen Technician	 Work Permit in place Competent Technicians with proper training Restricted to use of identified walkways 	Low
Vehicle Access Working in Car Parking Areas	Fire Queen Technician Customer Employee Member of Public	 Work Permit in place Competent Technicians with proper training Parking in designated areas where possible Parking in agreed areas with suitable warning signs 	Low
Area/Room Access	Fire Queen Technician	 Work Permit in place Competent Technicians with proper training Escorted by Contractor representative if required 	Low

Email: enquiries@firequeen.co.uk