

IMPORTANT PLEASE READ

17/06/2019

Twinflex Flashpoint 302-0012 Low Profile, 302-0022 Domed & 302-0023 Weatherproof

It has come to our attention that there is a potential issue with the **Twinflex Flashpoint**

The **Flashpoint** is designed to react as follows: when the panel sounds alarm, the sounder will sound and the flashpoint will flash

UNPLANNED OPERATION

However, an unplanned operation on the panel has been detected: when the panel sounds alarm the sounder will sound and the flashpoint will flash, in some circumstances the panel will briefly show a fault on the zone, this will not affect the alarms sounding and will automatically clear

PANELS IMPACTED

This only affects Twinflex Flashpoint 302-0012 Low Profile, 302-0022 Domed & 302-0023 Weatherproof

RESOLUTION

We advise that the function of the Twinflex Flashpoint 302-0012 Low Profile, 302-0022 Domed & 302-0023 Weatherproof should not be affected by the panel briefly showing fault.

An update to the components has been made and released.

Due to this recent update, a new revision of the Twinflex battery calculator 26-1116-11 is now available

Please contact our Technical Department on: 01633 865558, option 2 for further advice. We appreciate your business.

****End of bulletin****